


Left Side Impact, Front-View

Note that sensor locations and ISO Codes are different for right side impact.
Note that the IR-TRACC device fitted to this dummy records a voltage.
It is more normal to exchange the displacement channel.



Note that sensor locations are not fixed: transducers are taped in position as required. ISO Codes used must reflect the chosen position. FL1 should reflect the side, LE or RI, for these channels, if used.

